

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	15	"6263466"	US- PGPUB; USPAT	OR	ON	2008/04/25 15:01
L5	1	"6263466".pn.	US- PGPUB; USPAT	OR	ON	2008/04/25 15:01
L6	1	5 and CRC	US- PGPUB; USPAT	OR	ON	2008/04/25 15:02
L7	1	5 and (CRC "cyclic redundancy code")	US- PGPUB; USPAT	OR	ON	2008/04/25 15:03
L8	1	"5734815".pn.	US- PGPUB; USPAT	OR	ON	2008/04/25 15:07
L9	1	"4916704".pn.	US- PGPUB; USPAT	OR	ON	2008/04/25 15:32
L10	457	"network switch".ti.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L11	457	L10	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L12	6416	709/236,238,246.ccls.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L13	29	L12 and L10	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L14	29	L13	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L15	26	L13 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L16	26	L15	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L17	7369	frame same buffer same (switch router brouter bridge)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21

L18	7369	L17	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L19	3175	memory same frame same buffer same (switch router brouter bridge)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L20	3175	L19	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L21	27113	memory same frame same buffer	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L22	27113	L21	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L23	2	(memory same frame same buffer same (switch router brouter bridge)).ti.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L24	2	L23	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L25	2	L23 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L26	2	L25	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L27	63	(memory same frame same buffer) .ti.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L28	63	L27	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L29	58	L27 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L30	58	L29	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L31	2607	370/254,404,395.53.ccls.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L32	2607	L31	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L33	9147	370/389,392,393,462.ccls.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21

L34	9147	L33	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L35	1604	L33 and (port\$1 interface) same (v\$1lan tag\$1 label\$1 \vlan)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L36	1604	L35	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L37	323	L35 and frame same buffer	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L38	323	L37	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L39	177	L35 and frame same buffer same (switch router bridge)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L40	177	L39	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L41	166	L39 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L42	166	L41	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L43	98	L41 and (update updating swap swapping remov\$3 insert \$3) same (tag header "vlan tag")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L44	98	L43	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L45	2607	370/254,404,395.53.ccls.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L46	2607	L45	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L47	0	L45 same (vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L48	0	L47	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L49	105	L45 and (vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21

L50	105	L49	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L51	12	L45 and ((vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)). ab.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L52	12	L51	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L53	7	L51 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L54	7	L53	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L55	534	Saxena.in.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L56	534	L55	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L57	22	Saxena adj1 rahul.in.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L58	22	L57	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L59	10	(CRC "Cyclic redundancy code") with ethernet near3 switch\$3	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L60	10	L59	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L61	8	L59 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L62	8	L61	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L63	1	"6151322".pn.	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
L64	1	L63	US- PGPUB; USPAT	OR	ON	2008/04/25 16:21
S1	1	"20050044261"	US- PGPUB; USPAT	OR	ON	2007/03/22 18:33

S2	5470	709/236,238,246.ccls.	US- PGPUB; USPAT	OR	ON	2007/03/22 18:34
S3	406	"network switch".ti.	US- PGPUB; USPAT	OR	ON	2007/03/22 18:34
S4	26	S2 and S3	US- PGPUB; USPAT	OR	ON	2007/03/22 18:35
S5	24	S4 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/10/07 11:02
S6	6552	frame same buffer same (switch router brouter bridge)	US- PGPUB; USPAT	OR	ON	2007/03/23 13:24
S7	2870	memory same frame same buffer same (switch router brouter bridge)	US- PGPUB; USPAT	OR	ON	2007/03/23 13:24
S8	24076	memory same frame same buffer	US- PGPUB; USPAT	OR	ON	2007/03/23 14:04
S9	2	(memory same frame same buffer same (switch router brouter bridge)).ti.	US- PGPUB; USPAT	OR	ON	2007/03/23 13:24
S10	2	S9 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/03/23 18:11
S11	59	(memory same frame same buffer) .ti.	US- PGPUB; USPAT	OR	ON	2007/03/23 14:04
S12	55	S11 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/03/23 18:05
S13	2053	370/254,404,395.53.ccls.	US- PGPUB; USPAT	OR	ON	2007/03/23 18:06
S14	7303	370/389,392,393,462.ccls.	US- PGPUB; USPAT	OR	ON	2007/03/23 18:07
S15	1299	S14 and (port\$1 interface) same (v\$1lan tag\$1 label\$1 vlan)	US- PGPUB; USPAT	OR	ON	2007/03/23 18:09
S16	294	S15 and frame same buffer	US- PGPUB; USPAT	OR	ON	2007/03/23 18:10
S17	159	S15 and frame same buffer same (switch router bridge)	US- PGPUB; USPAT	OR	ON	2007/03/23 18:10

S18	153	S17 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/03/23 18:25
S19	90	S18 and (update updating swap swapping remov\$3 insert \$3) same (tag header "vlan tag")	US- PGPUB; USPAT	OR	ON	2007/03/23 18:27
S20	2053	370/254,404,395.53.ccls.	US- PGPUB; USPAT	OR	ON	2007/03/25 15:38
S21	0	S20 same (vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)	US- PGPUB; USPAT	OR	ON	2007/03/25 15:41
S22	81	S20 and (vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)	US- PGPUB; USPAT	OR	ON	2007/03/25 15:41
S23	9	S20 and ((vlan v\$1lan) same (remov\$3 updat\$3 add\$3 insert \$3) same (tag header lable)). ab.	US- PGPUB; USPAT	OR	ON	2007/03/25 15:41
S24	7	S23 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/03/25 15:42
S25	495	Saxena.in.	US- PGPUB; USPAT	OR	ON	2007/10/07 10:55
S26	20	Saxena adj1 rahul.in.	US- PGPUB; USPAT	OR	ON	2007/10/07 11:01
S27	9	(CRC "Cyclic redundancy code") with ethernet near3 switch\$3	US- PGPUB; USPAT	OR	ON	2007/10/07 11:02
S28	8	S27 and (@rlad<"20030718" @ad<"20030718")	US- PGPUB; USPAT	OR	ON	2007/10/07 11:02
S29	1	"6151322".pn.	US- PGPUB; USPAT	OR	ON	2007/10/07 11:15
S30	13	("20020061022"   "20020174399"   "20030002506"   "20030152076"   "20040068689"   "20050232270"   "20060274755"   "6151322"   "6515993"   "6535218"   "6680945"   "6745246"   "6975627").PN.	US- PGPUB; USPAT	OR	ON	2008/04/23 22:22
S31	3	S30 and ("cyclic redundancy check" "cyclic redundancy code")	US- PGPUB; USPAT	OR	ON	2008/04/23 22:23

---

4/25/2008 4:26:19 PM

C:\Documents and Settings\THussain1\My Documents\EAST\Workspaces\10622287.wsp